

4m,9,35.

12 JUN 1939

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *"Juno"*

Rpt. *Hul.*

No. *49981*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey

DAMAGE.

Damage through *heaving the anchors (See also Hul Rpt. No 49842)*

now repaired as follows:-


	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:- *Vessel afloat & permanent repairs effected to the hull class.*

It is submitted the vessel is worthy to remain as classed without record of Survey & without special condition.

as now, without, etc.

SSW1 had on hull.



© 2021

Lloyd's Register
Foundation

W416-0122