

P.S. "Turo"

Hull. 33268.

It is submitted that the Hull  
Surveyors be requested to state if they  
are correct in reporting the length of  
stem bush to be 10" observing that the  
diameter of the screw shaft is  $10\frac{3}{8}$ ".



© 2024.

Ans.

7/3/21.

Lloyd's Register  
Foundation

W416-0132