

LEITH.

30th. April, 1919.

J.R. Henderson,

the Managing Owners survey the Steel Screw Steamer "WOLFSBURG" of  
London 6165 tons gross register Capt. H.W. Pantin, for the purpose  
of ascertaining and reporting upon the damage stated to have been  
caused through colliding with the "KRONENFELS" on the 10th. April,  
1919.

The following damage was found and repairs recommended:-

FOUND.

Port side in way of forward  
rigging bulwark plates indented  
bulb plate bulwark stanchion  
bent and twisted.

RECOMMENDED.

Bulwark plate to be faired in place.  
Bulb plate stanchion to be removed,  
faired and replaced.

Fee = £2:2:-

Surveyor to Lloyd's Register.



© 2019

Lloyd's Register  
Foundation

WHP-0217