



*Doublets along bottom continuous
but may be broken with Riv. later on
Deck below doublets later and Riv.
later on later*

ALTERATIONS			
ISSUE	REMARKS	DESCRIPTION	DATE
1	0	COAL HATCH ADDED	25-17

THICKNESS OF MATERIAL	.24 TO .34				.36 TO .48				.50 TO .66				.68 TO .88			
	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	INCHES	
DIA. OF RIVETS	5/16"	3/8"	1/2"	5/8"	3/4"	1"	1 1/8"	1 1/4"	1 1/2"	1 3/4"	2"	2 1/8"	2 1/4"	2 1/2"	2 3/4"	
STRINGER BUTTS	3"	3"	3"	3"	3"	3"	3"	3"	3"	3"	3"	3"	3"	3"	3"	
DECK BUTTS	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
DECK LAPS	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
BEAMS	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
GUNWHALE	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
HATCH	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
CASING	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
W.T. B.K.D.	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
VENTILATORS	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
MAST RING	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
GIRDER ANGLES	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
SHELL CLIPS	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
INSIDE STRINGER ANGLE	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
NON W.T. B.K.D. ANGLES	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
HATCH DOUBLING PLATES	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	
DOUBLING PLATES UNDER DECK	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	1"	

APPROVED
APR 23 1940
LLOYD'S REGISTER OF SHIPPING
NEW YORK

UPPER DECK PLATING

SCALE: 1"=1' FOOT. DATE: 4-22-18
THE ATLANTIC CORPORATION
DRAWN BY: M.A.
CHECKED BY: M.A.
APPROVED: M.A.

Lloyd's Register
Foundation

"Guatemala" ex VALIENTE Reg. N.Y. No 40295