

B. 2m, 131.

FREEBOARD REPORT on the

British Endeavour

the oceanic Superintendent

Mr. Church states over the telephone that the normal closing appliances in the poop front openings are storm boards in riveted channels. He also states that the hook bolts fastening the portable steel plates will be altered to pass through portable plate only.

J.C. 18/8/32



© 2019

Lloyd's Register
Foundation

W421-0179