



Lloyd's Register of Shipping,

201, Tower Building,

Liverpool, 20th August 1920.

Dear Sir,

With reference to the Secretary's letter of the 19th inst regarding the Liverpool first entry report No 80758 on the S.S. Ben Seyr ex "Venron", I beg to inform you that the $\frac{3}{4}$ " rivets in the bulks of the shell plating are spaced $3\frac{1}{2}$ inches apart as required, and not 3" as stated on the report.


I regret the clerical error.

I am dear sir,

Yours faithfully

W.W. Cole

The Secretary
Liverpool.



© 2020

Lloyd's Register
Foundation