

King are expected to make good headway in getting the water out of the

BEULAH. has been

TELEPHONE: SEYMOUR 2022

TELEGRAPHIC ADDRESS: "REGISTRAR" VANCOUVER



Lloyd's Register of Shipping

BRITISH COLUMBIA

1319 MARINE BUILDING
VANCOUVER, B.C.

LLOYD'S REGISTER
Received
8 APR 1938
LONDON

March 26th, 1938

The Secretary,
Lloyd's Register of Shipping,
London, E.C.3.

Initial R.

M.V. "BEULAH".

Dear Sir:-

I have to acknowledge your letter of March 15th. enclosing a copy of your letter of the same date, to the Owners of the M.V. "BEULAH".

This vessel has now been raised, and in company with the Owners' and Underwriters' Surveyors I examined the ship on dry dock at Victoria yesterday.

There is practically no under water damage, but considerable repairs will be necessary internally and to the erections, accommodations, bridge and main deck, the latter having collapsed.

Specifications have been drawn up, and tenders will be received on March 29th., after which a decision regarding repairs, or otherwise, will be made.

In my opinion the cost of repairs will very nearly reach the insured value.

Yours very truly,

A. Scott
Surveyor.

Lloyd's Register
Foundation
16285

