

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

7th May, 1923.

Dear Sirs,

With reference to your First Entry Report No.2537 on the Motor Vessel "HEIREN", I shall be glad if you will be good enough to state:-

1. Whether the sheathing of the poop and forecastle decks is as approved, and not as reported.
2. Whether the riveting of the edges and butts of shell, poop and forecastle side plating is as required by the Rules, and not as reported as regards the shell plating.
3. Whether the masts have been fitted as approved, as this is not clear from the report.
4. Whether the test of the first bower anchor is correct as reported, as it would appear the "10 cwt" reported should read "18 cwt".
5. Whether the equipment as regards hawsers and warps reported represents all those placed on board, in view of the fact that as a steamer those required under Table 31 of the Rules should be

hawsers - 2 @ 90 fms. $2\frac{1}{2}$ S.W. or 6" manilla.
warps - 2 @ 90 fms. $1\frac{1}{2}$ S.S. or 5" manilla.

© 2020

Lloyd's Register
Foundation

W425-0094 (112)

W425-0094 (112)

- 2 -

and not as stated for sailing vessels, Table 30 of the
Rules.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

CHRISTIANIA.



© 2020

Lloyd's Register
Foundation

W425-0034 (42)