

Received from Chief Ship Surveyor

Ship Surveyor

NAME Steel non-propelling Bucket Dredger
Yard No. 520

Rot No. 24752

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

This vessel has left Rotterdam for Aberdeen to have ~~the~~ machinery installed.

It is submitted the Aberdeen Surveyors be advised, and requested to forward a report on form 8 to this Office when the survey has been completed.

To complete the survey see report.

Yes
21.8.36

THK

It is concluded the spacing of the bulkhead stiffeners is as approved, but the ~~Surveyors~~ ^{Rotterdam} should state if this is so.

No. 22.8.36



© 2020

Lloyd's Register
Foundation

W425-0206

32

2.32

0 x .3

3 1/2 x .3

34