

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office \_\_\_\_\_ 19

# Lloyd's Register of Shipping.

(Report on Vessel No. 390192 Port Hull)



No. F. 20155 SHIP FORGINGS OR CASTINGS.

be struck out as may be required.

I have to report that the undermentioned Iron or Steel Forgings or Castings, manufactured by Messrs Emerson Walker Ltd of Dunston-on-Tyne for the Vessel No. 07V 284, being built by (repaired by) Gode S & Co of Goole have been inspected by me as set forth below and found to be, so far as can be seen, Sound.

work on Forgings or Castings.

Lloyd's  
No. 8058  
JD  
1.9.28

(Stock) J Dale  
Newcastle.

	STERN FRAME.	RUDDER FRAME.	STEM.
Material* ...	<u>Scrap iron</u> <u>Forged</u> <u>5' dia</u> <u>Forging &amp; machining</u> <u>1.9.28</u>		
How made † ...			
Dimensions ...			
Progress on Inspection ...			
Date when Inspected ...			
<b>CASTINGS.</b>			
Tests on Standard Test Pieces.			
Tensile Test—			
Tons per square inch			
Extension per cent. ...			
Cold Bending Test—			
Angle before fracture			
Drop Test—			
Height from ground ...			
Hammering Test—			
If made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ 1 : 1 : 0 MONTHLY A/C.

To be paid at


NEWCASTLE-ON-TYNE.

© 2020

\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

9.25. T.

† State if annealed \_\_\_\_\_



Lloyd's Register  
W 432-0171