

S. S. Mangalore

It is concluded that a set of adjusting liners
have been placed on board, but as this is not
included in the list of spare gear, it is
submitted the Glasgow Surveyors be requested
to state if this is so.

JWZ ~~At~~ 20/6/20.

Lloyd's Register
Foundation

W432-0205