

Port of Mangalore

11th July

1928

disfactory & repaired the vessel & relaid the

10.12.19. H.

2

REPORT ON MASTS, SPARS, AND RIGGING.

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

M. C. Mangalore

Report

No. 48214

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/23.)

No.

2

SURVEY PARTLY HELD.

Voyage

When due

6. 28

When proposed to be completed

on return from present


Portion of Survey held, &c.,

RETAIN

To complete Survey see Report

Duty.

Scarp of stem frame EW again 5. 24 & 7. 28 to be specially examined at next Pz working



© 2020

Lloyd's Register Foundation

W432-0277

Fee L

4 P.h