

seams DR. D.B.S. Diameter of rivet holes in <sup>circ. seams</sup> 1 5/16" Pitch of rivets 1 1/2"

Engine No. 6321 Made by Stechin C.E. & Riley Boilers

Boiler For S.S. "Liberton"

Udd. Report No. 16407

It is submitted that ~~a copy of this Report~~ be forwarded ~~returned~~ to the NWC. Surveyors for their guidance and for completion.

Date 13/8/38.



© 2019

Lloyd's Register Foundation

Send NWC:-

W433-0093

of stays to into: Sizes 1 1/2 2 1/2 Back 7/4 8 1/2 Top 8 1/2 Are stays fitted with nuts or rivets