

Report, No. 111517

Port Liv

*100A1 12.37

f Surveyors

Received from Chief Surveyors

NAME

COUNSELLOR

Report

Liv.

No. 113101

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

1st S.S. No 3

When due

8,38

Noted

af
16.9.39



© 2019

Lloyd's Register
Foundation

W433-0098

Fastenings	- do -	Ceiling	0 - do -	Coal Bunkers, Open'gs, Lids, &c.	- do -	Boats	
Plating	- do -	Cement or Asphalt	- do -	Oil Bunkers	✓	Masts, Yards, &c.	
					good	Condition how ascert	