

GROSS 207 1/2  
UNDER DK. 283 1/2

Owners *Thynell SS 68.7M.*

Owners' Address  
(if not already recorded in Appendix to Register Book & ...)

4m, 9, 35.

0761 NOV 9 11

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

THURSTON

Rpt. CFF

No. 53236

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Particulars of Survey

Damage through *ice*

now repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed .....							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

*Vessel placed in dry-dock, bottom coated,  
a bower anchor and 15 fms of chain cable  
renewed and minor repairs effected*

It is submitted the vessel is worthy to remain as classed with  
record of Survey 12-39.

100 A.1

12-39 CFF

*WAG*  
15-1-40

The S.S. 2<sup>nd</sup> No. 2 becomes due 1-40.

© 2019

Lloyd's Register  
Foundation

W435-0080

This vessel as now seen is in good condition and eligible in ...