

W436-0138

2m, 10, 33.

1

33.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 23 APR 1934

VESSEL'S NAME Stl. S. WILLOWPOOL

Rpt. Hpl No. 17344

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey DAMAGE.

Damage through striking lock wall (Lon 99826)

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	9						
removed and faired	6						
or repaired.....							
Faired or repaired		1					
in place.....							

Other items:- Vessel placed in drydock, bottom cleaned & coated
Stem bar faired and minor repairs effected

It is submitted the vessel is worthy to remain as classed with
record of Survey 3.34 as recommended.

100A.1.
3.34 Hpl

delete. Stem & stem plating from SRL



21.4.34

2019
Lloyd's Register
Foundation