

4m,9,35.

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

VOREDA

Rpt.

MCH.

No. 9818

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

grounding

now repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed .....	4	1 PI					
Removed and faired or repaired.....	4	4					
Faired or repaired in place.....	5	1		5			

Other items:-

Vessel placed in dry-dock, bottom coated

Lower stem bar renewed, bilge keels + pump room bulkhead repaired and minor repairs effected.

It is submitted the vessel is worthy to remain as classed with record of Survey 12-39.

100A-1.

12-39 MCH.

Carrying petroleum in bulk  
Fitted for oil fuel etc.

was  
21-12-39.

*[Signature]*



© 2019

Lloyd's Register  
Foundation  
W436-0169