

Rpt. 11b.

TUES 24 JUL 1906

CARDIFF

27396

Lloyd's Register of British & Foreign Shipping.

SURVEYS FOR FREEBOARD.

PARTICULARS IN RESPECT OF STEAM SHIPS WITH TOP GALLANT FORECASTLES, HAVING LONG POOPS OR RAISED QUARTER DECKS CONNECTED WITH BRIDGE HOUSES, OR SHORT POOP AND BRIDGE HOUSE DISCONNECTED, OR BRIDGE HOUSE.

Port of Survey

CARDIFF

July 21st 1906.

Date of Survey

Name of Surveyor

Arthur Scullard.

Delete words which do not apply.

Ship's Name.

Gross
Tonnage.Official
Number.

Type of Ship.

Date of Build.

Particulars of Classification.

"Hungarian" *Wicklow of East*
Number in Register Book 953

1487

80452

187 (Im-W.S.)

2 b. B.

1879

3

+ 100 A. I.

Registered Length as { 260 ✓ Breadth 35.2 Depth 18.4
shown by ship's register.

Length on Loadline 260.0 ✓

Breadth 35.2 ✓

Depth 18.4 ✓ Tons und. Dk. 12 4/4
Correction for excess or deficiency of Gradual Sheer (Para. 8) ... 11 ✓
..... 18.59 ✓ × 100

Depth to be used 18.59 ✓

Moulded Depth as measured 19.11 ✓

NOTE.— If the depth is measured when vessel is afloat, the details of measurement should be reported.

Co-efficient of fineness

Any modification necessary [Para. 4 (a) to (e)*]

Co-efficient as corrected 0.375 ✓

CORRECTION FOR LENGTH.

Length of Ship on Loadline 260.0 ✓
Length in Table 239.0 ✓
Difference 21.0 ✓

Correction for 10ft., Table A. 1.18 ✓ Table C. 1.26 ✓

× Difference divided by 10 2.478 (if required.)

If $\frac{1}{10}$ ths length covered divide by 2 } for vessels coming under Para. 11 } + 2.2 ✓ + 1.2 ✓

and Para. 12 }

CORRECTION FOR IRON DECK.

Proportion covered, if less than $\frac{1}{10}$ ths length covered

Thickness of usual wood deck, less stringer

Wood sheathed

NOTE.— The round of beam should be reported on the full breadth of vessel at the gunwale.

CORRECTION FOR ROUND OF BEAM.

Breadth at Gunwale amidships

Round of Beam 9 1/2 ✓

Normal round 8 1/2 ✓

Difference 1 1/2 ✓ ÷ 2 = 1/2 ✓

Proportion of Deck uncovered (Para. 19) 4.2 - 4 ✓

Rise in Sheer { At front of bridge house.
from amidships { Lowest point of sheer amidships
[Para. 18 (e)] At after end of forecastle

ALLOWANCE FOR DECK ERECTIONS:—

Freeboard, Table C. 1 " 3 1/2 ✓
Correction for Length, if required (Para. 12 and 18) + 6.5 1/4 ✓
Freeboard by Table A. corrected for sheer, and for length, if required (Para. 12 and 18) 14 " 1
Difference 2 " 8 1/4
Percentage as below. 3 1/4 76 ✓

Freeboard, Table A. 3' 9 1/2 ✓
Correction for Sheer 1
Correction for Length 3' 10 1/2 ✓
Allowance for Deck Erections 4" 1 ✓
Correction for Round of Beam 3' 0 1/4 ✓

Correction for engine and boiler openings not being covered by bridge house, in cases coming under Para. 11

Allowance for Deck Erections 1" 0 1/2

	Length.	Length allowed.	Height.
Forecastle	32.0 ✓	32.00	6' 6" ✓
Bridge House	66.0 ✓	66.00	4' 6" ✓
+ Raised Qr. Dk.	52.5 ✓	50.84 ✓	4" 0" ✓
Poop	✓	✓	✓
Total	150.5	148.84 ✓	5 1/2 ✓
Length of Ship	260.0	260.00	5 1/2 ✓

Corresponding percentage (Para. 11, 12, or 18.) { 34.7670 ✓

FREEBOARD recommended amidships from centre of Disc to top of Statutory Deck Line, Wood (Iron) Deck:—

Fresh Water Line	above centre of Disc
Indian Summer Line	" "
Winter Line	below "
Winter North Atlantic Line	" "


the frames skin planking or ceiling are of unusual thickness the breadth of vessel to inside of ceiling should be reported if possible.
In vessels containing an allowance for deck erections under Para. 11 where the sheer drops abaft amidships the height of the P.Q.D. is to be taken from the level of the top of the amidship beam.

Correction necessary because clear side amidships measured in accordance with the Statutes is not taken at the intersection of the wood or iron deck with side. } + " 1/2 ✓

Winter Freeboard	3' 0 1/2 ✓
Summer Freeboard	2' 9 1/2 ✓
N. A. Winter Freeboard	3' 2 1/2 ✓

Winter Freeboard from deck line S	3' 2" ✓
Summer " " " "	2' 11" ✓
N. A. Winter, " " "	3' 4" ✓

State dimensions of freeing port area on back of this form
Marked in accordance with Sec. 437, M. S. Act, 1894



© 2019

Lloyd's Register
Foundation
W437-0269

DELETE WORDS WHICH DO NOT APPLY.

The Crew ~~are~~ are not berthed in the bridge house.

The arrangements to enable them to get backwards and forwards from their quarters ~~are, are not~~ satisfactory.

Length of Bulwarks in well

Area of freeing ports required by Para. 11 (e) each side of vessel

Sq.Ft.

Freeing Ports (each side of vessel)

Ft. Tenths. Ft. Tenths. No.

x x }

 =

Sq. Ft.

x x }

Total deficiency = 7841

Sq. Ft.

Total excess =

"

Vertical distance from bottom of keel or from top of deck at side amidships to lower edge of lowest side scuttle.

(N.B.—This dimension need not be reported unless the sill of the lowest side scuttle would be less than 6 inches above the Indian Summer Load Line if assigned under the tables.)

Do all the Frames extend to the top height in the Poop ?

Do. do. do. in the Raised Quarter Deck ?

Do. do. do. Bridge House ?

Do. do. do. Forecastle ?

To what height do the Reverse Frames extend ?

Has the Poop or Raised Quarter Deck an efficient Iron Bulkhead at the fore end ? Yes.

Give particulars of the means for closing the openings in Bulkhead. No openings

Is the Poop or raised Quarter Deck connected with the Bridge House ? No.

State whether the Bridge House efficiently covers the Engine and Boiler Openings Yes.

Has the Bridge House an efficient Iron Bulkhead at the fore end ? Yes.

Give particulars of the means for closing the openings in Bulkhead. No openings.

Describe how and to what extent it is stiffened, give scantlings and spacing of Angle Irons, Bulb

Plates, etc. By $4\frac{1}{2}$ - $3\frac{1}{2}$ Angles spaced about 30° apart.

Has the Bridge House an efficient Iron Bulkhead at the after end ? Yes, 1 Cายo Port 18×18 4'-8" from Wood

How are the openings closed ? By a hinged Iron Door with a clip.

Is the forecastle at least as high as the main or top-gallant rail ? Higher



Has the Forecastle an efficient Iron or Wood Bulkhead at its after end ? Yes

Are the Hatchways efficiently constructed ? Yes What is the thickness of the Hatches ? $2\frac{1}{2}$

State the height of the Coamings in fore well ? No. 1 & 2 33" from Wood 10".

Are the exposed parts of the Engine and Boiler Casings efficiently constructed ? Yes

State any special features in the construction of the Vessel



Show hereon the actual measurements of sheer, draft, erections, breaks in line of floors, &c.

Owners Hungarian S.S. Co. Ltd (W. Morgan Lewis)

Address

Cardiff

© 2019

Fee £ 3 : 3 : .
Applied for 23.7.06

Received by me

Lloyd's Register
Foundation