

Capacity ... tons; MT ... feet ... tons.
N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides ...

CHARACTER.
* for Special Survey.
Date of last Survey and of Periodical Surveys.

27 MAR 1936 4

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME CABO PALOS

Rpt. Gen

No. 14420

Acts of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.

COMPLETION OF 1st S.S. No 2 DUE 1.35

The 1st S.S. No. 2 partly held at Genoa

Completed, and the following repairs done (due to wear & tear):-
placed in dry dock bottom cleaned & coated
minor repairs carried out

is submitted the vessel is worthy to remain as classed, with record
5.36 and notation of S.S. No 2.35 ~~is recommended.~~

100 A1.

With freeboard

5.36 Gen

S.S. Gen No 2.35

22.5.36

h/

W438-0273



© 2020

Lloyd's Register Foundation

(per Section 29) Comp. S.S. No 2 L1E.430.-
Condition " 320.-
Special Damage or Repair Fee (if any) £

Fees applied for, 11/5/36.

RETAIN

RETAIN



© 2020

Lloyd's Register
Foundation

N. B.
If t
of the tan
girders, a

Last

(Periodic
cause
on acc
and b
replac
the bu

In dama
offe

REPAIR
NOW

found

made

REPA
COND

& co

SUMMARY

Rem
Rem
Fair

PRESENT

Decks

Caulking of

Coamings

Beams & F

Outside Pla

" "

Breasthook

Transoms...

Frames

Reverse Fr

Longitudina

Transverses

Floors

Keelsons

Stringers...

Inner Botto

Gene

this
surv

surv

Survey Fee

Special P