

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

25th November, 1930.

Dear Sirs,

With reference to the entry in your return of vessels under survey relative to the motorship "CABO PALOS" I have to acquaint you I am in receipt of a report from the Society's Surveyors at Buenos Aires from which it appears that the bedplate of the main motor in way of No.3 main bearing seat (from forward) was found fractured vertically on each side of the cross member. Temporary repairs were effected and the Surveyors recommend that the bedplate should be again examined on the vessel's arrival at a home port.

I shall be glad if you will be guided accordingly.

I am, Dear Sirs,

Yours faithfully,

pro Secretary.

The Surveyors,

GENOA.

C. J. L.



© 2020

Lloyd's Register
Foundation

W 438-0327