

Do. of Houses on Deck
Do. of excess of Hatchways

28-94

Length on deck from fore part of stem to after part of
stempost

230

By whom built Campbell

Imp. 14

1

Sent to Chief Surveyors

17. 6. 14

Received from Chief Surveyors

VESSEL'S NAME

St. S. Cato

Report

JK

No.

16707

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

First Entry

When due

+ 100 A. 1 (Steel) Shelter deck with futboard
1 JK (St) Shelter deck (St)
N.B. Hull 53' a E.D. 33' f' 213t. A.P. 18t.
JK 4 B.H. "Cm. Lays A & B.P.

M
17. 6. 14
E. L. L.



© 2020

Lloyd's Register
Foundation

W439-0006

Spacing
BEAMS, Second, Third & Fourth Deck, Single
Angle Bulb Angle Plate Tee Bulb or Channel

44

44

Tie Plates, outside Hatchways
Deck Material and thickness