

BOARD REPORT on the Castlemoor

It is submitted the Sunderland Surveyors be requested to obtain the following information from the Builders, Messrs. W. Dorricks
Yard No 562


1. The moulded displacement at a moulded draught equal to 85 per cent. of the moulded depth;
2. The external displacements and tons per inch at actual draughts:- 29.

a reply by wire is requested

Lulla

5.6.29

cent



© 2020

0.13

Lloyd's Register
 Foundation

W439-0136

Drop in Sheer abaft amidships.....

$$\begin{array}{r} 46.25 \\ .55 \\ \hline = 84.09 \\ 52-00 \\ 36 \quad 32.09 \\ .89 \end{array}$$

nd of Spar-deck Beam.....13

„ Main-deck „13

Indian Summer Freeboard.....

N. A. Winter Freeboard.....

Correction necessary because of draught amidships.....

- 11 1/2
 + 5
 - 4 1/2
 - 0
 - 4 1/2
 2 - 4
 9 - 9
 - 3
 9 - 6
 9 - 6
 8 - 11
 8 - 5