

t. 6.

For the information of Surveyors and the Committee only.

Received at GREENOCK

Office

18 NOV 1933

# Lloyd's Register of Shipping.


(Report on Vessel No. 19423. Port GREENOCK )  
S.S. "HARTLEBURY"

No. 1895 SHIP ~~FORGINGS OR~~ CASTINGS.

to be struck out as may be required.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Messrs Dr. Shaw & Co. Ltd. of Middlesbrough for the Vessel No. 865, being built by Messrs Lithgow & Co. of Port Glasgow have been inspected by me as set forth below and found to be, so far as can be seen, sound and free from defects.

Work on Forgings or Castings.



Lloyd's  
No. 1895  
FC 15.11.33

Quadrant

Tiller

STERN FRAME.

RUDDER FRAME.

STEM.


Material*	S. M. Acid, Open Hearth Steel.	
How made	Cast	
annealed	Yes	
Dimensions	To patterns	
Progress on Inspection	Rough, rough bored, & faced.	
Date when Inspected	4. 4. 33	15. 11. 33
CASTINGS.		
Tests on Standard Test Pieces.		
Inside Test—		
Tons per square inch	29.6	28.6
Extension per cent. ...	27	32
Cold Bending Test—		
Angle before fracture	120°	120°
Drop Test—		
Height from ground ...	7 feet	10 feet.
Hammering Test—		
If made according to Rules and found satisfactory ...	Yes	Yes

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.



Fee (if any chargeable) £ Nil-Classed Vessel.

To be paid at



\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth Register.

m.329. T.

0. T.

Lloyd's Register of Shipping  
Foundation

W 44-00 38  
W 44-00 39 40

N<sup>o</sup> 865

Report on Quadrant  
& Siller.



© 2021

Lloyd's Register  
Foundation