

GLASSGOW REPORT No.

1E

Inspected by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME

Hartlebury

Rpt.

Es

No. *54332*

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Type of Engine

Triple expansion

3 cy. 22 1/2, 36 & 65 - 48

*Exhaust
Drum & Turbine driving steam
compressor.*

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of

approved type

*Yes.
Yes
No.*

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *SMC 3-34*

ES 3/4/34



© 2021

Lloyd's Register
Foundation

W 44-00 50

ing sq connections
in hold 2. 3 34 Boiler's fixed

Engines tried under steam

31


SEE 476.0M

188

188

© 2021

Lloyd's Register
Foundation



[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]

[Handwritten signature or initials in blue ink.]

Entry
older Fee
Expense

is Certificate
hile the C
derstood th
ntry in a
on of the s
yours, or o