

Engine Room ...
TONNAGE FOR FEES...
Less Engine Room
2336.97
1740.02

Deck at side to top of keel

Residence London

1,500,10,17.
1

Sonicstar

Sent to Chief Surveyors 21. 3. 18

Received from Chief Surveyors

VESSEL'S NAME *Shells Rubiera*

Report *Grk*

No. 17266

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

100A-1 (Steel) Shells DK with freeboard.
2 Dks (Steel) & Shells DK (Steel pl 105)
Cell D.B. 342' 9 1/2 L. F.P.T. 45 L. A.P.T. 24 L.
F.K. 6 BH. Cam. Lys as per. For Shells DK 50'
Date of Build 12.17

RETAIN

M
21. 3. 18

© 2021
Lloyd's Register
Foundation
Wh40-0007

BEAMS, Bridge Deck, Angle, Bulb Angle, Plate,
Tee Bulb or Channel

Angle on deck