

State latest date of internal examination of each boiler 24/7/37 To what pressure were they afterwards adjusted under steam? 180
Did the Surveyor examine the Safety Valves of the Main Boiler? Yes

5m. 9.37.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Bedrington Court

Report

Lev.

No.

112 535

Old

326 24

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

S. S. No 2

When due

12. 38

It is submitted that
this vessel is eligible for
THE RECORD.

+ Lev. 5. 39
S. 1. 39

Yrun

26. 7. 39



© 2021

Lloyd's Register
Foundation

CS 3,34, 120 to, F.P., etc.)

The machinery of this vessel, as now run, is in an efficient condition and eligible