

23 JAN 1935

Surveyor \_\_\_\_\_ Received from Chief Ship Surveyor \_\_\_\_\_  
Steel Sc. "JOYOUS" ex "JAMESON" Rpt. Ans. No. 13355a.

the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also  
out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points  
d in the endorsement. —Extract from Sub-Committee's Report, 24/5/32.

DAMAGE AND PART S.S. No. 1 after an early No 3.

rough striking submerged object.

red as follows:-

|           | Plates | Frames | R.Frames | Floors | Beams | Str. | Plates | Dk. | Plates |
|-----------|--------|--------|----------|--------|-------|------|--------|-----|--------|
| .....     | 7      |        |          | 3 pt   |       |      |        |     |        |
| nd faired | 8      | 8      |          | 4      |       |      |        |     |        |
| red.....  |        |        |          |        |       |      |        |     |        |
| repaired  | 10     | 38     |          | 41     |       |      |        |     |        |
| .....     |        |        |          |        |       |      |        |     |        |

RETAIN

s:-  
Ship placed in drydock, repairs to intercostals and  
repairs carried out, and the bottom coated.  
(after an early No 3)

a S.S. No. 1 due 3.35, has also been partly held and the  
repairs done due to wear and tear.-

proposed to complete the survey not stated.  
submitted ~~this proposal might be approved~~, and the vessel be  
to remain as classed with record of Survey 1.35. Notation of  
No. 1 being deferred until completion of same.

Following remains to be done to complete the

See Report.

S.S. No. 1

W443-0056

© 2020 Lloyd's Register Foundation