

Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,



Hull, 10th March 1924

Dear Sir,

In reply to the query contained in your classing letter of the 7th inst, regarding the screw shaft of the s.s. "HARFERY", I beg to inform you that this shaft does not run in oil, and is not fitted with an oil gland at the after end.

I regret that this was not made clear in my report.

In future cases, where oil glands are fitted the type of gland will be stated in the report.

I am, Dear Sir,

Yours faithfully,

John H. Mackinder.

The Secretary,

London E.C.3.



© 2020

Lloyd's Register
Foundation

W443-0107

to forward the usual letter from the owners.

Referred to the Chief Engineer Surveyor.

7am
11 MAR 1924

for Mr. S. A. Hill to note.

Noted
11/3/24



© 2020

Lloyd's Register
Foundation