

S. S. "Harfur"

This submitted the Hull Surveyors be informed that it is observed from their report 42781 dated 9.5.32, that the convention freeboards have been marked on the ship's sides and verified but that the requirements have not yet been complied with. It is noted that this will be done on the ship's return to Gooler shortly.

They should be reminded that the convention freeboards should not be marked until all the conditions of assignment are complied with.

16/5

W443-0147

© 2020 Lloyd's Register Foundation