

Inspected by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME SEA VENTURE Rpt. Nwc No. 97912

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE.

Damage through ice

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed .....	3	4 PART					
Removed and faired or repaired.....	6						1
Faired or repaired in place.....	5	4					

Other items:-

*Vessel placed in dry-dock, bottom coated and minor repairs effected.*

It is submitted the vessel is worthy to remain as classed with record of Survey 9-39.

100 A.1.  
9-39 SHL.

*WAB*  
*5-10-39*



© 2020

Lloyd's Register  
Foundation

W443-0168