

The remaining requirements of Sections of the Rules for Engines & Boilers 1938-9 to be complied with so far as they are applicable.

JOHN DICKINSON & SONS, ENGINEERS, LTD.
 TRACING No. 52/39
 DATE 27.4.39
 SUNDERLAND

CONTRACT 282
 DIAGRAM SHOWING SUCTION CONNECTIONS

ENGINES N° 890.


ss. "Stonegate"

J. Dickinson & Sons'
Con 282

Section Connections.

REMAIN

SUNDERLAND DIVISION 32672



© 2020

Lloyd's Register
Foundation

W443-0244