

LLOYD'S REGISTER
Received
17 MAY 1939
Ansd.
LONDON

H

(Received at London Office)

REQUEST FOR INSPECTION SERVICES.

WAJ/LS. 12724M.

DATE 16th May, 1939.

We confirm our request to the Committee of Lloyd's Register, that they will instruct the Society's Surveyors to inspect the Superheater Apparatus for the s.s. "Stonegate". Tubes at Tubes Ltd., Birmingham, (Fee £2. 12. 6.) already inspected.

at The Superheater Co., Ltd., Mosley Road, Trafford Park, Manchester (Fee £2. 2. 0.) and we agree to pay the ~~fees and expenses~~ incurred for inclusive charge of £4. 14. 6. these services. total for ship's set.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

NAME OF FIRM THE SUPERHEATER CO., LTD.,

ADDRESS BUSH HOUSE, ALDWYCH,

LONDON, W.C.2.

After signature, please return this form to:

THE SECRETARY,
LLOYD'S REGISTER OF SHIPPING,
71, FENCHURCH STREET,
LONDON, E.C.3.



Lloyd's Register
Foundation
W443-0259

(Req. 8a). 2m.12.36.

