

10.38.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor **23 AUG 1939**

VESSEL'S NAME

"WAIKOUAITI"

Rpt.

Dun.

No.

2277

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

It is submitted before this case receives the consideration of the Committee, the Dunedin Surveyor be informed it is concluded that the sheerstrake plating amidships and at ends, the strake below at ends and the bridge side plating, have been drilled and found satisfactory, but he should state if this is so, and the results available for these drillings should be forwarded for inclusion in the Report.

*Classed
20/8*

*J.W.
19.8.39*

J.W.



© 2021

Lloyd's Register
Foundation

WHL5-0000

examined. Shell? Safety drill listed as per Rules and found to be as per attached sheet. The remainder in shell plating and some 10 ft but is...

rema
be exp
n. 7
d.
exam
replac
plac

Wood Vessels
(Felt.)
Month

ertained
ges removed)

4
33
SA

arranged)
70
d) 270

ing Rigging

Book consequ
nd to have r

tion
+100.

with spot records of survey 7.39., and at notation ss Odn. 2nd No. 3-39. In...