

Lloyd's Register of Shipping,

NOT FITTED.

W446-0047

5m.7.30.

30 SEP 1931

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "GREENBATT"

Rpt.

Nwc.

No. 81564

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Nature of Survey

The Newcastle Surveyors report a new donkey boiler has been fitted and a repair effected to the tank top in way of same and the tank tested on completion of the repair.

It is submitted the vessel appears worthy to remain as classed without record of survey.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2020 Lloyd's Register Foundation

30.9.31

Lawyer & Warps
standing and Running