

Last Report No. \_\_\_\_\_ Port \_\_\_\_\_  
Particulars of Examination and Repairs (if any) BS.

for Special Survey.  
Date of last Survey and of Periodical Surveys. +100A1 4031.  
2m. 4.31.  
2E

Received by Chief Engineer Surveyor Greenbatt Received from Chief Engineer Surveyor KWC.  
VESSEL'S NAME Greenbatt Rpt. KWC. No. 81584.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.

This Survey, due 6.91 now ~~partly~~ held at ~~now~~

~~completed~~, and the following repairs carried out (due to wear & tear):-

New Souhey Boiler fitted  
Minor repairs to main Boilers

RETAIN

It is submitted the vessel is eligible to remain as classed, with notation of BS 9-21 as recommended.  
NDA 21.

2019/21



© 2020

Lloyd's Register Foundation

Special Damage or Repair Fee (if any)..... £ 1 : 1 : -  
(per Section 29.)  
Travelling expenses (if chargeable)..... £ : : -

Received by me, 29.10.1931

L. J. Skett & J. Stodd  
Engineer Surveyor to Lloyd's Register

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

tested and  
dent.  
If Stockless, state Mechanical Tests

tested and  
dent.