

N.B.—All alterations in the existing records should be underlined.

Last Report. No. 97309 Port Nwc.

+ 100 A1

by Chief Ship Surveyor

Received from Chief Ship Surveyor

2/10/39

EL'S NAME

"DAGHESTAN".

Rpt.

Nwc.

No.

97894.

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

It is submitted before this case receives the consideration of the Committee the Surveyors be requested to state whether repairs have been effected to fractured shell plate No.7 in 3rd below sheer from forward, starboard side, recommended to be dealt with before the vessel proceeded to sea.

yes Mr. C. B. 3/2/39

29.9.39

Class? Ltr to Nwc: - 3/2



© 2019

Lloyd's Register
Foundation

Transverse Frames

Longitudinals

cient?

Have Sluice Valves been examined and found off-

Planking

Caulking

Treennails

Anchors, No. of

Cables (State if no

RETAIN



© 2019

Lloyd's Register
Foundation