

Twin S.S. "SULTAN STAR".

Mr. E. A. Thomson, the Superintendent of the Blue Star Line, has telephoned this morning that they have had a further cablegram from this vessel from which it appears that the port engine has now broken down badly after the vessel left St. Vincent on her way home.

Instructions have been given for the vessel to return to St. Vincent, using her starboard engine, which has been kept in reserve.

Mr. Thomson states that they have two other vessels in the vicinity of the "SULTAN STAR", one outward bound in light condition and the other returning home loaded, and messages have been sent to these vessels to proceed to the "SULTAN STAR", and they are hoping that the vessel will return to St. Vincent without further mishap.

The question as to how best to deal with the matter after her return to St. Vincent is to be specially considered.

Mr. Thomson proposes coming over this morning to consult with Mr. Ruck-Keene regarding the matter.

4th March, 1930.



© 2020

Lloyd's Register
Foundation

W448-0193