

Date 28th February 1930

BLUE STAR LINE (1920) LTD.,

Head Office: LONDON.

Received from STEAMER SULTAN STAR

ST VINCENT C.V.I.

Code Words

Translation

PORT engine main wheels intact stop Secondary
 pinions outboard intact stop Inboard after end
 intact fore end three teeth broken to length
 of six inches stop Primary wheels intact stop
 Pinions all intact stop Starboard engine main,
 wheels after wheel completely stripped stop
 Forward wheel one fractured tooth broken for two
 inches on forward end stop Secondary pinions
 outboard after end completely stripped^{stop}/forward
 end intact but bruised stop Inboard after end
 completely strapped stop Forward end eight teeth
 broken three inches long stop Primary wheels
 outboard after section intact stop Forward section
 stripped two inches full circumference stop
 Inboard intact stop Pinions high pressure intact
 stop Intermediate intact stop Low pressure stripped
 two inches full circumference stop all instructions
 having attention



Lloyd's Register
Foundation

W448-0195