

ALL COMMUNICATIONS TO BE ADDRESSED TO THE COMPANY.

BLUE STAR LINE (1920) LTD

TELEPHONES:
AVENUE 8020 (4 LINES).
AVENUE 3404/5 (2 LINES).

TELEGRAMS:
"BLUESTARLI, STOCK, LONDON"

CODES:
WATKINS 1904 EDIT. BENTLEY'S PHRASE,
SCOTT'S, A.B.C. 5th EDITION.

PASSENGER OFFICE:
3, REGENT STREET,
LONDON, S.W. 1.

BRANCH OFFICES:
DOCK BOARD BLDG., LIVERPOOL,
BUENOS AIRES & SANTOS.



40, St. Mary Axe,

London.
E.C.3.

IN YOUR REPLY PLEASE
QUOTE REFERENCE EAT/SNC.

25th February, 1930.

Secretary,
Lloyd's Register of Shipping,
71 Fenchurch Street, E.C.3.



Dear Sir,

"SULTAN STAR".

We have to advise that the above vessel reports from Lat. N.8, while outward bound, that difficulties have developed in the reduction gearing of main engines and which will necessitate returning to builders for repair. Meanwhile, she is returning at reduced speed to St. Vincent and is due to arrive there on Thursday morning, the 27th inst., and will then send us a full report of the condition of the gearing.

We understand that you have no surveyor at St. Vincent and that it will be necessary to apply to Lloyd's Agent to appoint a surveyor.

Yours faithfully,
For BLUE STAR LINE (1920) LTD.

E.A. Thomson

Senior Superintendent.



© 2020

Lloyd's Register
Foundation

W448-0208

Referred to the Chief Engineer Surveyor.

as

26 FEB 1930

Also for Mr. S. A. Hill to note.

Spl

LONDON

30 FEB 1930

RECEIVED



© 2020
Lloyd's Register
Foundation