

s/s "Joyce Llewellyn"

Abn 13582.

It is submitted the Aberdeen Surveyors should be requested to state whether an approved oil retaining gland has been fitted to the after end of the stern tube, as this is not clear from their report.

Lr 11/7/24

Yes.
See Abn. No.
2/7/24

JWD

28/6/24

© 2020



Lloyd's Register
Foundation

W469-0017