

22 FEB 1940

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "SINT ANNALAND" .

Rpt. Ant.

No. 23148.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Antwerp Surveyors report both bower anchors and 4 lengths of chain cable on each side missing.

A second hand bower anchor and one length of chain cable have been placed on board. No markings could be seen on the anchor and no test certificate for either the anchor or cable were produced.

The Surveyors recommend ^{the} a bower anchor and length of chain cable ^{now} be placed on board ^{be} and verified with certificates, and another bower anchor and 3 lengths of chain cable be placed on board at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As now, subject etc.

ces
21.2.40

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register
Foundation

W669-0197