

17 DEC 1934

"KOSMOS"

Got 9982.

Submitted the Gothenburg Surveyors' attention be drawn to the fact that no pressure is recorded in the Register Book for 12 of the Press Boilers.

The reason for this was that nothing was known in this Office regarding the scantlings of these 12 boilers.

It is observed that the Surveyors state in the heading of their report that there are 12 Press Boilers at 60 lb. pressure and that they have adjusted all the safety valves under steam.

Reports on these 12 boilers have now come to hand and it appears that the scantlings are suitable for a pressure of 3 kg. only.

The Gothenburg Surveyors were out of order in assuming a pressure which was not recorded in the Register Book and in the circumstances they should point out to the Owners that the 12 Hartman Boilers are to be worked at a pressure not exceeding 3 kg. per cm^2 , and arrange for the safety valves to be re-adjusted to that pressure at the earliest opportunity.

[Signature]
17/10/34

L. Joh. 21. 12. 34



© 2021

Lloyd's Register
Foundation

W45-0138