

W450-0134

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"YORKSHIRE"

Report

Lw

No.

112931

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

Condition

When due

Subject to indented shell plating port side
abreast N^o 2 hatchway & abreast No 5 hatchway
port side & to indented shell plates No 17 & 15
from forward port side in 2nd & 3rd strakes
respectively below sheer being dealt with at
owner's convenience.

without other condition

Sh. Amend the entry in S.P.f. :-
to

Shell plating p.s.f.
as above
because 17 & 15 plates from forward
not p.s.f.



© 2020

Lloyd's Register
Foundation