

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME WHITEMANTLE Rpt. Wuc. No. 97923

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Remarks of Surveyor

The Newcastle Surveyors report this vessel placed in dry dock, bottom cleaned and coated, repairs or renewals to hatchways and minor repairs effected.


The Steering chains have been repaired and retested.

It is submitted the vessel appears worthy to remain as classed with record of survey 9.39 as recommended.

100 A1
9.39 Wuc.

The Certificate of Classification to be endorsed “Cargo battens not fitted” and the same notation to be printed in the Register Book.

9.10.39



© 2019

Lloyd's Register
Foundation

W451-0083