

S.S. "CITY OF MANDALAY"

It is submitted the attached sketch of solid ~~floor~~ and bracket floors be forwarded to the Newcastle Surveyors, who should be requested to indicate in red ink the correct position of the intercostal, stiffeners on floors, and arrangement of manholes, in accordance with the vessel as built, and to return the sketch by return of post in order that the First Entry Certificate may be prepared.

Their attention should also be drawn to the requirement, as stated in the First Entry Report, that plans showing the vessel as built should be forwarded, and that in all future cases plans of the vessel as built must accompany the First Entry Report.

20.1.25

© 2020

Lloyd's Register
Foundation

It is concluded that the floorboard marks have been cut in on the side but the surveyors should be requested to state if this is so.