

If the Vessel has Water Ballast Tanks, state whether the
of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,
girders, and of the inner bottom plating, especially in the boiler space.

POSTPONED SURVEYS.

Case of the Steel S.S. "BLYTHMOOR".

8478 in Reg. Bk. 6582/4032 tons, Built 1922-3

10081 Owners W. Runciman & Co.

Shelter deck with fld T. 12.31 Port of Registry London

2-31 11.31 thru 2.31

Due Boiler Survey due February, 1932.

At the beginning of April last the Owners stated they hoped this vessel would return to this Country in about three or four months when the above survey would be held, and in the circumstances the Committee agreed to the inspection being postponed for a time.

rs
ome
weeks
ey
h
with

The Owners have now informed the Newcastle Surveyors that this vessel is expected to be home from Australia in five or six weeks' time when the above survey will be held.

Submitted for approval provided Boiler Survey be held as promised J.D. 8/11/32

tee's Minute FRY 12 AUG 1932

Deferred Subject

Only



© 2020

Lloyd's Register Foundation

remain as assessed