

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler spaces.

for Special Survey.
Date of last Survey and of
Periodical Surveys.

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

5th April, 1932.

Dear Sirs,

I beg to acknowledge the receipt of your letter of the 1st instant intimating that the Boiler Survey of the steamer "BLYTHMOOR" will be carried out on the vessel's return to this Country, which you anticipate will take place in three or four months' time.

In reply I have to say that in the circumstances the Committee, who had the case before them at their Meeting today, are agreeable to the survey in question being postponed for the present.

I am, Dear Sirs,

Yours faithfully,

pro Secretary.

Messrs. Walter Runciman & Co., Ltd.,
Pilgrim Street,
NEWCASTLE/TYNE.



© 2020

Lloyd's Register
Foundation

remain as classed & to have record of survey