

N.B.—All alterations in the existing records should be...  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

+100A1...  
for Spec...  
Date of last Su...  
Periodical

NEWCASTLE 23333-23337  
LONDON MONUMENT 4500



TELEGRAMS { RUNCIMAN NEWCASTLE-ON-TYNE  
MOORISH FEN LONDON  
SCOTTS CODE 10TH EDITION

# WALTER RUNCIMAN & CO. LTD.

SHIPOWNERS & BROKERS

(LONDON) LTD  
DENHALL STREET,  
LONDON, E.C.3.



PILGRIM STREET,  
NEWCASTLE-UPON-TYNE.

JHG

1st April 1932  
Friday.

Messrs. Lloyds Register of Shipping,  
London.

Sirs,

We have your yesterday's letter regarding Boiler  
on the "BLYTHMOOR", and in reply we beg to advise you  
matter will have our attention on vessel's return to this  
try in, we hope, three or four months' time. We trust  
will be satisfactory to your Committee.

Yours faithfully,

FOR AND ON BEHALF OF  
WALTER RUNCIMAN & CO. LD.

*Walter Runciman* DIRECTOR



© 2020

Lloyd's Register  
Foundation

WHS-0025

remain as classed & to have record of su

Freebo...  
Lon Sh...  
, by w...  
ru...  
la...  
d...  
m...  
Other...  
✓  
ad...  
✓  
od...  
"  
the vess...  
"to...  
le

Referred to Mr. S. A. Hill.

*hus*

2 APR 1932

*Ref done 2-22*



© 2020

Lloyd's Register  
Foundation

nk.  
the space fo

State  
is survey,  
vey, 1924.

erial

om Plating

ames

nals

es.

ating

Fastenings

of Decks

CONDIT

oved and

oved

Y OF DA

oved and

oved

CONDIT

oved and

oved

N.H.-All  
If the Vesse  
of the tanks exau  
and of th

Rep

ical Surgen  
s of Repa  
count of  
besides be  
ement o  
each of the

age cases  
red his s

RS, OR