

Name of Vessel *S.S. "Lesreaults"*  
*ex "Punmore"*

No. in Register Book .....

	FEET.	INCHES.
Moulded Depth . . . . .	28	6 1/2
Stringer Plate . . . . .		1/2
Thickness of wood sheathing if required . . . . .		✓
Statutory deck line above intersection of <u>actual</u> deck at side . . . . .		2
Total depth from top of statutory deck line to top of keel . . . . .	28	9
Freeboard recorded . . . . .	3	6 1/2
Moulded Draft . . . . .	25	2 1/2
Add for keel—Flat or <del>Bar</del> . . . . .		2 1/4
Draught . . . . .	25	4 3/4
Draught for record . . . . .	25	5



© 2020

Lloyd's Register  
 Foundation

W454-0198



REPAIR



© 2020

Lloyd's Register  
Foundation

eer { Stem.  
t { Stern

eer at  $\frac{1}{4}$  of

radual mean

andard mea

If limited

Rise in Sh

rom amidsh

Para. 18 (a)

Fall in Sh

Para. 18

length unco

of wood sheathing if required

T, tharboard

correction f

board b

ifference

percentage a

board recorded

rection f

covered

owance f

ecastle.

dge Hous

aised Q

p.....

Total

length of Sh

espondin

Para. 11,

EEBOA

27

the frames, a

of ceiling sh

reels obtain

the heli

us-decked

port. In ves

one-eighth of