

Lloyd's Register of Shipping,

2, Laidlaw Building,
Battery Road,

Singapore, 22nd March, 1939

ENCLOSURE

Dear Sir,

I enclose herewith a cutting from the local press relative to the foundering of the Motorship "MALINI".

From an unofficial source, I have learnt that the explosion occurred in an air receiver fitted close to the ship's side and forward bulkhead of the engine room.

I am, Dear Sir,

Yours faithfully,

John Wormald

The Secretary,
London.



© 2020

Lloyd's Register
Foundation

W458-0020

23222

Referred to Mr. Dyer

31 MAR 1939

Mr. Dyer
The Secretary
London.

Dear Sir,

I am, Dear Sir,

ENGINE ROOM.

close to the engine and towards the bow of the ship. The explosion occurred in an air receiver fitted

below an engine room. I have found

"MAY 1939"

please refer to the forwarding of the Motorist

I enclose herewith a cutting from the Local

Dear Sir,
ENCLOSURE

Lloyd's Register
Foundation

Engine, Motorist, 1939
Battery Road,
Building,
3, Gaiety Building